

Soprane CDS

Prerequisites



Dear user,

Thank you for choosing this SRA Instruments product.

This manual contains all the necessary information for the correct use of your software. Should you need further information or if you encounter any problems, please contact our After Sales Service:

Hotline: +33 (0)4 78 44 22 09
E-mail: service@sra-instruments.com


 <p>SRA INSTRUMENTS ANALYTICAL SOLUTIONS</p>	<p>SRA Instruments 210 rue des Sources 69280 Marcy l'Etoile FRANCE</p>	<p>Tel : +33 (0)4 78 44 29 47 Fax : +33 (0)4 78 44 29 62 info@sra-instruments.com www.srainstruments.com</p>
--	--	--

Table of contents

1. TYPE OF CONNECTION TO THE COMPUTER	4
2. COMPUTER	4
3. ELECTRICAL OUTLETS	4

1. Type of connection to the computer

Equipment	LAN	RS 232	RS485	WIFI
MicroGC 990	1			
MicroGC 490	1			
MicroGC 3000 RS		1*	1*	
MicroGC 3000 Lan	1			
GC 7890 / GC 7820	1			
GC 8890 / GC 8860	1			

* RS ports can be replaced by USB/RS converter(s)

2. Computer

OS	Processor speed		Memory	
	Minimum	Recommended	Minimum	Recommended
Windows 7/8.1/10/11	2 GHz (Core i3)	3 GHz (Core i5)	4 GB	8 GB

- For Windows 7, SP1 version only
- For Windows 10, version 1903 and higher.

3. Electrical outlets

Equipment	220 V	110 V
MicroGC 490	1	
MicroGC 490 WIFI option	1	
MicroGC 990	1	
GC 7890 / GC 7820	1	
GC 8890 / GC 8860	1	